TSD RCRA Inspection Report

EPA Identification Number: _1_ _N_ _O_ _O_ _7_ _7_ _O_ _O_ _5_ _9_ _1_ _6_

Installation Name: _Gary Land Development_

Location Address: _479 North Cline Ave._

City: _Gary_   ZIP _46401_

Date of Inspection: _8-27-87_   Time of Inspection _10:30 AM_

Person(s) interviewed *	Title	Telephone
Mr. Larry Hagen	Vice President	219-944-7858

Inspector(s)	Agency	Telephone
Ted Warner	IDEM	317-232-4303
Jonathan Copper	U.S. EPA	312-886-4464

* Please identify correspondence contact

Installation Processes by Process Code (EPA Form 3510-3)

SO1 ___	Container storage	SO2 ___	Tank storage	
SO3 ___	Waste Pile storage	SO4 ___	Surface impoundment storage	
D79 ___	Injection well disposal	D80 _X_	Landfill disposal	
D81 ___	Land Application disposal	D83 ___	Surface Impoundment disposal	
TO1 ___	Tank Treatment	TO2 ___	Surface Impoundment treatment	
TO3 ___	Incinerator treatment	TO4 ___	Other	

If Part A process codes are listed above as TO4 please describe the process involved below.

_____

Other activities

Generator _X_   _conditionally-exempt small quantity generator D001_
   Appendix GN

Transporter ___
   Appendix TR

1.   Indicate any hazardous waste processes, by process code, which have been omitted from Part A of the facility's permit application.

2.   Indicate any hazardous waste processes (by process code and line number on EPA Form 3510-3 page 1 of 5) which appear to be eligible for exclusion per 40 CFR 265.1(c). Provide a brief rationale for the possible exclusion.

13. Additional Comments

This facility has not attempted to meet any applicable RCRA or 320 IAC 4.1 requirements. Noncompliance is the same as my last inspection on 8-22-86.
See field trip report.